



## SAFETY RULES

- \* Report all injuries, no matter how small, to the Shed Boss.
- \* Know the locations of first aid kits, fire extinguishers, and exits.
- \* Wear safety glasses in the shop environment, even if you are not working at a machine.
- \* Tie up long hair and/or beards so they do not get caught in machines.
- \* No loose clothing, such as ties, scarves, loose sleeves, etc.
- \* No open-toed shoes. Shoes should provide sure footing.

- \* Be aware of what is going on around you. Take care not to bump into others.
- \* Stay alert and concentrate on what you are doing. If you are tired, leave.
- \* If something about a machine doesn't sound right, turn it off and report it to the Shed Boss.
- \* If you are unsure about how to do something, ask.
- \* Do NOT leave machines running unattended.
- \* Do NOT operate any machinery for which you have not been cleared by Shed staff.